

Returning Industrial & Natural Gas Cells



Wrong Way



NOT packaged correctly. No cap, not secured in bubble wrap, allowing element to contact foam during transport causing a broken element.

Right Way



To secure cell, wrap element in bubble wrap.



Place bubble wrapped cell in a box with a sufficient amount of packing peanuts to prevent damage to cell.