

Returning Industrial APZ / APRZ Cells



Wrong Way




NOT packaged correctly. No cap, not secured in bubble wrap, allowing element to contact foam during transport causing a broken element.

Right Way



Packaged correctly and tightly to secure battery and harness in place. DO NOT connect to cell.



Place cell in foam cutout to secure for transport.



Final packaging top layer added to secure and protect cell.

